



ENGLISH:

1. We disassemble the ASIC and pull out the control board so that access to the SD slot appears, you can turn off the power (6pin) from all the hash boards and the Internet and leave the power to the control board if desired
2. Turn off the power and rearrange the jumpers on the control board Initially, the jumper controls are like this:



We put them in this position:



3. Turn on the control board with an inserted SD card and wait 60 seconds before the LEDs blink.

4. Turn off the ASIC, pull out the USB flash drive, rearrange the jumpers

5. VNISH firmware is installed